


Avaya Power Supply 1151D1 Connecting and Troubleshooting Telquest tech Support



Special Note:

The power for the Busy Lamp Module is passed to the phone on Pins 7 and 8.

Many Category 5 Data Patch Cords may not have a through connection from Pins 7 and 8.

This is because they only need Pins 2, 3, 4, and 6 for Data.

If the Busy Lamp Module does not work, test to see if the DC Voltage is present on Pins 7 and 8 at the end of the cord that plugs into the phone.