

AVAYA S/W NOTICE

In order for this card to operate, the Control Unit has to be running the 2Q11 Service Pack release for 6.1 or 7.0 or later releases.
The card is not supported on Version 6.0 and earlier releases.