


# PERFORMANCE ROLLER EXCHANGE KITS FOR BETTER SCANNING

*Keep your scanners running in tip-top shape with new roller exchange kits*

**CONTACT US TODAY!**

**B2Bsales@us.panasonic.com | 877-207-0035**



SCANNER MODEL #	ROLLER PART #	RECOMMENDED REPLACEMENT CYCLE
KV-S7097	KV-SS015	300,000 Sheets Scanned
KV-S7075C		
KV-S7065C		
KV-S3065CL	KV-SS017	300,000 Sheets Scanned
KV-S3065CW		
KV-S3065CL	KV-SS018 (thin paper)	300,000 Sheets Scanned
KV-S3065CW		
KV-S2026C	KV-SS024	300,000 Sheets Scanned
KV-S2028C		
KV-S2045C		
KV-S2046C		
KV-S2048C		
KV-S3085C	KV-SS026	300,000 Sheets Scanned
KV-S3105C		
KV-S3085C	KV-SS027 (thin paper)	300,000 Sheets Scanned
KV-S3105C		
KV-S4065CL / CW	KV-SS033	300,000 Sheets Scanned
KV-S4085CW		
KV-S1020C	KV-SS035	100,000 Sheets Scanned
KV-S1025C		
KV-S1045C		
KV-S5055C	KV-SS039	350,000 Sheets Scanned
KV-S1026C / KV-S1026C-MKII	KV-SS058	100,000 Sheets Scanned
KV-S1037X		
KV-S1046C		
KV-S1065C		
KV-S1015C	KV-SS059	100,000 Sheets Scanned
KV-S5046H	KV-SS060	350,000 Sheets Scanned
KV-S5076H		
KV-S1027C / KV-S1027C-MKII	KV-SS061	250,000 Sheets Scanned
KV-S1057C / KV-S1057C-MKII		
KV-N1028X		
KV-N1058X		
KV-S2087	KV-SS063	350,000 Sheets Scanned
KV-S8127	KV-SS100	600,000 Sheets Scanned
KV-S8147		
KV-S8147	KV-SS101*	3,600,000 Sheets Scanned

\*Includes 6 sets of feed rollers.

**LEARN MORE**

**us.panasonic.com/scanners**